



Sterling 1835 Town Hall

Progress Report October 17, 2018

1835 Town Hall Committee

Looking North West from Town Hall
Main Street and Houghton Road



Looking West from Town Hall
Main Street & Rts 12 and 62



Looking North from Town Hall
Main Street & Route 12



Looking South from Town Hall
Maple St, School Street, Pine Street



Town Hall Roof
Aerial Photograph




Great Hall – Before We Began



Structure Bay #3 – Before
Junction Timber Frame with Rod and Cable



Structure- Before
Junction Timber Purlin and Rafter Beam



Great Hall – Current
View from Gallery



Structure - Current
Temporary Supporting Structure



Structure - Current
LVL Sandwich Beam



Bay #4


Building LVL Sandwich

Purlin

Collar Tie

Structure - Current

LVL Sandwich Beam at Ridge



Structure - Current
LVL Sandwich Beam



Building LVL Sandwich
At Ridge



14 Ply LVL




Structure - Current
LVL Sandwich Beam



Bay #4
LVL Sandwich


Structure - Current

LVL Sandwich Beam



Structure - Current

LVL Sandwich Beam



Structure - Current

LVL Sandwich Beam



Structure - Current
Elevator (LIFT) Shaft

